

Hannay Reels, Inc. 553 State Route 143, Westerlo, NY 12193 www.hannay.com Email: reels@hannay.com Phone 1-518-797-3791 Toll Free 1-877-GO-REELS (467-3357) Fax 1-800-REELING (733-5464) Int'l Fax 1-518-797-3259


## TSB 2019.05.002

## Split Bearing Part Identification Guide

Affected Reels: All 1-1/2"Reels

Date Issued: September 2019

## NOTE: AS 01/01/2019 ALL 1-1/2" REELS ARE BUILT WITH A SPLIT BRONZE BEARING ON THE JOINT SIDE



## NOTE:

Refer to ISO-211 for full bearing parts list including full bearing assemblies available at hannay.com. Refer to TSB 2019-05-001 for installation/replacement instructions available at hannay.com.